

ProdID	Description	I.D.	O.D.	X-Section
AS-001	Buna O-Ring (70 DUROMETER)	1/32	3/32	1/16 (0.070)
AS-002	Buna O-Ring (70 DUROMETER)	3/64	9/64	1/16 (0.070)
AS-003	Buna O-Ring (70 DUROMETER)	1/16	3/16	1/16 (0.070)
AS-004	Buna O-Ring (70 DUROMETER)	5/64	13/64	1/16 (0.070)
AS-005	Buna O-Ring (70 DUROMETER)	7/64	15/64	1/16 (0.070)
AS-006	Buna O-Ring (70 DUROMETER)	1/8	1/4	1/16 (0.070)
AS-007	Buna O-Ring (70 DUROMETER)	5/32	9/32	1/16 (0.070)
AS-008	Buna O-Ring (70 DUROMETER)	3/16	5/16	1/16 (0.070)
AS-009	Buna O-Ring (70 DUROMETER)	7/32	11/32	1/16 (0.070)
AS-010	Buna O-Ring (70 DUROMETER)	1/4	3/8	1/16 (0.070)
AS-011	Buna O-Ring (70 DUROMETER)	5/16	7/16	1/16 (0.070)
AS-012	Buna O-Ring (70 DUROMETER)	3/8	1/2	1/16 (0.070)
AS-013	Buna O-Ring (70 DUROMETER)	7/16	9/16	1/16 (0.070)
AS-014	Buna O-Ring (70 DUROMETER)	1/2	5/8	1/16 (0.070)
AS-015	Buna O-Ring (70 DUROMETER)	9/16	11/16	1/16 (0.070)
AS-016	Buna O-Ring (70 DUROMETER)	5/8	3/4	1/16 (0.070)
AS-017	Buna O-Ring (70 DUROMETER)	11/16	13/16	1/16 (0.070)
AS-018	Buna O-Ring (70 DUROMETER)	3/4	7/8	1/16 (0.070)
AS-019	Buna O-Ring (70 DUROMETER)	13/16	15/16	1/16 (0.070)
AS-020	Buna O-Ring (70 DUROMETER)	7/8	1	1/16 (0.070)
AS-021	Buna O-Ring (70 DUROMETER)	15/16	1-1/16	1/16 (0.070)
AS-022	Buna O-Ring (70 DUROMETER)	1	1-1/8	1/16 (0.070)

AS-023	Buna O-Ring (70 DUROMETER)	1-1/16	1-3/16	1/16 (0.070)
AS-024	Buna O-Ring (70 DUROMETER)	1-1/8	1-1/4	1/16 (0.070)
AS-025	Buna O-Ring (70 DUROMETER)	1-3/16	1-5/16	1/16 (0.070)
AS-026	Buna O-Ring (70 DUROMETER)	1-1/4	1-3/8	1/16 (0.070)
AS-027	Buna O-Ring (70 DUROMETER)	1-5/16	1-7/16	1/16 (0.070)
AS-028	Buna O-Ring (70 DUROMETER)	1-3/8	1-1/2	1/16 (0.070)
AS-029	Buna O-Ring (70 DUROMETER)	1-1/2	1-5/8	1/16 (0.070)
AS-030	Buna O-Ring (70 DUROMETER)	1-5/8	1-3/4	1/16 (0.070)
AS-031	Buna O-Ring (70 DUROMETER)	1-3/4	1-7/8	1/16 (0.070)
AS-032	Buna O-Ring (70 DUROMETER)	1-7/8	2	1/16 (0.070)
AS-033	Buna O-Ring (70 DUROMETER)	2	2-1/8	1/16 (0.070)
AS-034	Buna O-Ring (70 DUROMETER)	2-1/8	2-1/4	1/16 (0.070)
AS-035	Buna O-Ring (70 DUROMETER)	2-1/4	2-3/8	1/16 (0.070)
AS-036	Buna O-Ring (70 DUROMETER)	2-3/8	2-1/2	1/16 (0.070)
AS-037	Buna O-Ring (70 DUROMETER)	2-1/2	2-5/8	1/16 (0.070)
AS-038	Buna O-Ring (70 DUROMETER)	2-5/8	2-3/4	1/16 (0.070)
AS-039	Buna O-Ring (70 DUROMETER)	2-3/4	2-7/8	1/16 (0.070)
AS-040	Buna O-Ring (70 DUROMETER)	2-7/8	3	1/16 (0.070)
AS-041	Buna O-Ring (70 DUROMETER)	3	3-1/8	1/16 (0.070)
AS-042	Buna O-Ring (70 DUROMETER)	3-1/4	3-3/8	1/16 (0.070)
AS-043	Buna O-Ring (70 DUROMETER)	3-1/2	3-5/8	1/16 (0.070)
AS-044	Buna O-Ring (70 DUROMETER)	3-3/4	3-7/8	1/16 (0.070)
AS-045	Buna O-Ring (70 DUROMETER)	4	4-1/8	1/16 (0.070)
AS-046	Buna O-Ring (70 DUROMETER)	4-1/4	4-3/8	1/16 (0.070)
AS-047	Buna O-Ring (70 DUROMETER)	4-1/2	4-5/8	1/16 (0.070)
AS-048	Buna O-Ring (70 DUROMETER)	4-3/4	4-7/8	1/16

				(0.070)
AS-049	Buna O-Ring (70 DUROMETER)	5	5-1/8	1/16 (0.070)
AS-050	Buna O-Ring (70 DUROMETER)	5-1/4	5-3/8	1/16 (0.070)
AS-102	Buna O-Ring (70 DUROMETER)	1/16	1/4	3/32 (0.103)
AS-103	Buna O-Ring (70 DUROMETER)	3/32	9/32	3/32 (0.103)
AS-104	Buna O-Ring (70 DUROMETER)	1/8	5/16	3/32 (0.103)
AS-105	Buna O-Ring (70 DUROMETER)	5/32	11/32	3/32 (0.103)
AS-106	Buna O-Ring (70 DUROMETER)	3/16	3/8	3/32 (0.103)
AS-107	Buna O-Ring (70 DUROMETER)	7/32	13/32	3/32 (0.103)
AS-108	Buna O-Ring (70 DUROMETER)	1/4	7/16	3/32 (0.103)
AS-109	Buna O-Ring (70 DUROMETER)	5/16	1/2	3/32 (0.103)
AS-110	Buna O-Ring (70 DUROMETER)	3/8	9/16	3/32 (0.103)
AS-111	Buna O-Ring (70 DUROMETER)	7/16	5/8	3/32 (0.103)
AS-112	Buna O-Ring (70 DUROMETER)	1/2	11/16	3/32 (0.103)
AS-113	Buna O-Ring (70 DUROMETER)	9/16	3/4	3/32 (0.103)
AS-114	Buna O-Ring (70 DUROMETER) (15.54x2.62)	5/8	13/16	3/32 (0.103)
AS-115	Buna O-Ring (70 DUROMETER)	11/16	7/8	3/32 (0.103)
AS-116	Buna O-Ring (70 DUROMETER)	3/4	15/16	3/32 (0.103)
AS-117	Buna O-Ring (70 DUROMETER)	13/16	1	3/32 (0.103)
AS-118	Buna O-Ring (70 DUROMETER)	7/8	1-1/16	3/32 (0.103)
AS-119	Buna O-Ring (70 DUROMETER) (23.47x2.62)	15/16	1-1/8	3/32 (0.103)
AS-120	Buna O-Ring (70 DUROMETER)	1	1-3/16	3/32 (0.103)
AS-121	Buna O-Ring (70 DUROMETER)	1-1/16	1-1/4	3/32 (0.103)
AS-122	Buna O-Ring (70 DUROMETER)	1-1/8	1-5/16	3/32 (0.103)
AS-123	Buna O-Ring (70 DUROMETER)	1-3/16	1-3/8	3/32 (0.103)

AS-124	Buna O-Ring (70 DUROMETER)	1-1/4	1-7/16	3/32 (0.103)
AS-125	Buna O-Ring (70 DUROMETER)	1-5/16	1-1/2	3/32 (0.103)
AS-126	Buna O-Ring (70 DUROMETER)	1-3/8	1-9/16	3/32 (0.103)
AS-127	Buna O-Ring (70 DUROMETER)	1-7/16	1-5/8	3/32 (0.103)
AS-128	Buna O-Ring (70 DUROMETER)	1-1/2	1-11/16	3/32 (0.103)
AS-129	Buna O-Ring (70 DUROMETER)	1-9/16	1-3/4	3/32 (0.103)
AS-130	Buna O-Ring (70 DUROMETER)	1-5/8	1-13/16	3/32 (0.103)
AS-131	Buna O-Ring (70 DUROMETER)	1-11/16	1-7/8	3/32 (0.103)
AS-132	Buna O-Ring (70 DUROMETER)	1-3/4	1-15/16	3/32 (0.103)
AS-133	Buna O-Ring (70 DUROMETER)	1-13/16	2	3/32 (0.103)
AS-134	Buna O-Ring (70 DUROMETER)	1-7/8	2-1/16	3/32 (0.103)
AS-135	Buna O-Ring (70 DUROMETER)	1-15/16	2-1/8	3/32 (0.103)
AS-136	Buna O-Ring (70 DUROMETER)	2	2-1/8	3/32 (0.103)
AS-137	Buna O-Ring (70 DUROMETER)	2-1/16	2-1/4	3/32 (0.103)
AS-138	Buna O-Ring (70 DUROMETER)	2-1/8	2-5/16	3/32 (0.103)
AS-139	Buna O-Ring (70 DUROMETER)	2-3/16	2-3/8	3/32 (0.103)
AS-140	Buna O-Ring (70 DUROMETER)	2-1/4	2-7/16	3/32 (0.103)
AS-141	Buna O-Ring (70 DUROMETER)	2-5/16	2-1/2	3/32 (0.103)
AS-142	Buna O-Ring (70 DUROMETER)	2-3/8	2-9/16	3/32 (0.103)
AS-143	Buna O-Ring (70 DUROMETER)	2-7/16	2-5/8	3/32 (0.103)
AS-144	Buna O-Ring (70 DUROMETER)	2-1/2	2-11/16	3/32 (0.103)
AS-145	Buna O-Ring (70 DUROMETER)	2-9/16	2-3/4	3/32 (0.103)
AS-146	Buna O-Ring (70 DUROMETER)	2-5/8	2-13/16	3/32 (0.103)
AS-147	Buna O-Ring (70 DUROMETER)	2-11/16	2-7/8	3/32 (0.103)
AS-148	Buna O-Ring (70 DUROMETER)	2-3/4	2-15/16	3/32 (0.103)
AS-149	Buna O-Ring (70 DUROMETER)	2-13/16	3	3/32

				(0.103)
AS-150	Buna O-Ring (70 DUROMETER)	2-7/8	3-1/16	3/32 (0.103)
AS-151	Buna O-Ring (70 DUROMETER)	3	3-3/16	3/32 (0.103)
AS-152	Buna O-Ring (70 DUROMETER)	3-1/4	3-7/16	3/32 (0.103)
AS-153	Buna O-Ring (70 DUROMETER)	3-1/2	3-11/16	3/32 (0.103)
AS-154	Buna O-Ring (70 DUROMETER)	3-3/4	3-15/16	3/32 (0.103)
AS-155	Buna O-Ring (70 DUROMETER)	4	4-3/16	3/32 (0.103)
AS-156	Buna O-Ring (70 DUROMETER)	4-1/4	4-7/16	3/32 (0.103)
AS-157	Buna O-Ring (70 DUROMETER)	4-1/2	4-11/16	3/32 (0.103)
AS-158	Buna O-Ring (70 DUROMETER)	4-3/4	4-15/16	3/32 (0.103)
AS-159	Buna O-Ring (70 DUROMETER)	5	5-3/16	3/32 (0.103)
AS-160	Buna O-Ring (70 DUROMETER)	5-1/4	5-7/16	3/32 (0.103)
AS-161	Buna O-Ring (70 DUROMETER)	5-1/2	5-11/16	3/32 (0.103)
AS-162	Buna O-Ring (70 DUROMETER)	5-3/4	5-15/16	3/32 (0.103)
AS-163	Buna O-Ring (70 DUROMETER)	6	6-3/16	3/32 (0.103)
AS-164	Buna O-Ring (70 DUROMETER)	6-1/4	6-7/16	3/32 (0.103)
AS-165	Buna O-Ring (70 DUROMETER)	6-1/2	6-11/16	3/32 (0.103)
AS-166	Buna O-Ring (70 DUROMETER)	6-3/4	6-15/16	3/32 (0.103)
AS-167	Buna O-Ring (70 DUROMETER)	7	7-3/16	3/32 (0.103)
AS-168	Buna O-Ring (70 DUROMETER)	7-1/4	7-7/16	3/32 (0.103)
AS-169	Buna O-Ring (70 DUROMETER)	7-1/2	7-11/16	3/32 (0.103)
AS-170	Buna O-Ring (70 DUROMETER)	7-3/4	7-15/16	3/32 (0.103)
AS-171	Buna O-Ring (70 DUROMETER)	8	8-3/16	3/32 (0.103)
AS-172	Buna O-Ring (70 DUROMETER)	8-1/4	8-7/16	3/32 (0.103)
AS-173	Buna O-Ring (70 DUROMETER)	8-1/2	8-11/16	3/32 (0.103)
AS-174	Buna O-Ring (70 DUROMETER)	8-3/4	8-15/16	3/32 (0.103)

AS-175	Buna O-Ring (70 DUROMETER)	9	9-3/16	3/32 (0.103)
AS-176	Buna O-Ring (70 DUROMETER)	9-1/4	9-7/16	3/32 (0.103)
AS-177	Buna O-Ring (70 DUROMETER)	9-1/2	9-11/16	3/32 (0.103)
AS-178	Buna O-Ring (70 DUROMETER)	9-3/4	9-15/16	3/32 (0.103)
AS-201	Buna O-Ring (70 DUROMETER)	3/16	7/16	1/8 (0.139)
AS-202	Buna O-Ring (70 DUROMETER)	1/4	1/2	1/8 (0.139)
AS-203	Buna O-Ring (70 DUROMETER)	5/16	9/16	1/8 (0.139)
AS-204	Buna O-Ring (70 DUROMETER)	3/8	5/8	1/8 (0.139)
AS-205	Buna O-Ring (70 DUROMETER)	7/16	11/16	1/8 (0.139)
AS-206	Buna O-Ring (70 DUROMETER)	1/2	3/4	1/8 (0.139)
AS-207	Buna O-Ring (70 DUROMETER)	9/16	13/16	1/8 (0.139)
AS-208	Buna O-Ring (70 DUROMETER)	5/8	7/8	1/8 (0.139)
AS-209	Buna O-Ring (70 DUROMETER)	11/16	15/16	1/8 (0.139)
AS-210	Buna O-Ring (70 DUROMETER)	3/4	1	1/8 (0.139)
AS-211	Buna O-Ring (70 DUROMETER)	13/16	1-1/16	1/8 (0.139)
AS-212	Buna O-Ring (70 DUROMETER)	7/8	1-1/8	1/8 (0.139)
AS-213	Buna O-Ring (70 DUROMETER)	15/16	1-3/16	1/8 (0.139)
AS-214	Buna O-Ring (70 DUROMETER)	1	1-1/4	1/8 (0.139)
AS-215	Buna O-Ring (70 DUROMETER)	1-1/16	1-5/16	1/8 (0.139)
AS-216	Buna O-Ring (70 DURO) (s/a 28.17 x 3.53)	1-1/8	1-3/8	1/8 (0.139)
AS-217	Buna O-Ring (70 DUROMETER)	1-3/16	1-7/16	1/8 (0.139)
AS-218	Buna O-Ring (70 DUROMETER) (31.34x3.53)	1-1/4	1-1/2	1/8 (0.139)
AS-219	Buna O-Ring (70 DUROMETER)	1-5/16	1-9/16	1/8 (0.139)
AS-220	Buna O-Ring (70 DUROMETER)	1-3/8	1-5/8	1/8 (0.139)
AS-221	Buna O-Ring (70 DUROMETER)	1-7/16	1-11/16	1/8 (0.139)
AS-222	Buna O-Ring (70 DUROMETER)	1-1/2	1-3/4	1/8 (0.139)
AS-223	Buna O-Ring (70 DUROMETER)	1-5/8	1-7/8	1/8 (0.139)
AS-224	Buna O-Ring (70 DUROMETER)	1-3/4	2	1/8 (0.139)
AS-225	Buna O-Ring (70 DUROMETER)	1-7/8	2-1/8	1/8 (0.139)
AS-226	Buna O-Ring (70 DUROMETER)	2	2-1/4	1/8 (0.139)
AS-227	Buna O-Ring (70 DUROMETER)	2-1/8	2-3/8	1/8 (0.139)

AS-228	Buna O-Ring (70 DUROMETER)	2-1/4	2-1/2	1/8 (0.139)
AS-229	Buna O-Ring (70 DUROMETER)	2-3/8	2-5/8	1/8 (0.139)
AS-230	Buna O-Ring (70 DUROMETER)	2-1/2	2-3/4	1/8 (0.139)
AS-231	Buna O-Ring (70 DUROMETER)	2-5/8	2-7/8	1/8 (0.139)
AS-232	Buna O-Ring (70 DUROMETER) (Ref: 70 x 3.5)	2-3/4	3	1/8 (0.139)
AS-233	Buna O-Ring (70 DUROMETER)	2-7/8	3-1/8	1/8 (0.139)
AS-234	Buna O-Ring (70 DUROMETER)	3	3-1/4	1/8 (0.139)
AS-235	Buna O-Ring (70 DUROMETER)	3-1/8	3-3/8	1/8 (0.139)
AS-236	Buna O-Ring (70 DUROMETER)	3-1/4	3-1/2	1/8 (0.139)
AS-237	Buna O-Ring (70 DUROMETER)	3-3/8	3-5/8	1/8 (0.139)
AS-238	Buna O-Ring (70 DUROMETER)	3-1/2	3-3/4	1/8 (0.139)
AS-239	Buna O-Ring (70 DUROMETER)	3-5/8	3-7/8	1/8 (0.139)
AS-240	Buna O-Ring (70 DUROMETER)	3-3/4	4	1/8 (0.139)
AS-241	Buna O-Ring (70 DUROMETER)	3-7/8	4-1/8	1/8 (0.139)
AS-242	Buna O-Ring (70 DUROMETER)	4	4-1/4	1/8 (0.139)
AS-243	Buna O-Ring (70 DUROMETER)	4-1/8	4-3/8	1/8 (0.139)
AS-244	Buna O-Ring (70 DUROMETER)	4-1/4	4-1/2	1/8 (0.139)
AS-245	Buna O-Ring (70 DUROMETER)	4-3/8	4-5/8	1/8 (0.139)
AS-246	Buna O-Ring (70 DUROMETER)	4-1/2	4-3/4	1/8 (0.139)
AS-247	Buna O-Ring (70 DUROMETER)	4-5/8	4-7/8	1/8 (0.139)
AS-248	Buna O-Ring (70 DUROMETER)	4-3/4	5	1/8 (0.139)
AS-249	Buna O-Ring (70 DUROMETER)	4-7/8	5-1/8	1/8 (0.139)
AS-250	Buna O-Ring (70 DUROMETER)	5	5-1/4	1/8 (0.139)
AS-251	Buna O-Ring (70 DUROMETER)	5-1/8	5-3/8	1/8 (0.139)
AS-252	Buna O-Ring (70 DUROMETER)	5-1/4	5-1/2	1/8 (0.139)
AS-253	Buna O-Ring (70 DUROMETER)	5-3/8	5-5/8	1/8 (0.139)
AS-254	Buna O-Ring (70 DUROMETER)	5-1/2	5-3/4	1/8 (0.139)
AS-255	Buna O-Ring (70 DUROMETER)	5-5/8	5-7/8	1/8 (0.139)
AS-256	Buna O-Ring (70 DUROMETER)	5-3/4	6	1/8 (0.139)
AS-257	Buna O-Ring (70 DUROMETER)	5-7/8	6-1/8	1/8 (0.139)
AS-258	Buna O-Ring (70 DUROMETER)	6	6-1/4	1/8 (0.139)
AS-259	Buna O-Ring (70 DUROMETER)	6-1/4	6-1/2	1/8 (0.139)
AS-260	Buna O-Ring (70 DUROMETER)	6-1/2	6-3/4	1/8 (0.139)

AS-261	Buna O-Ring (70 DUROMETER)	6-3/4	7	1/8 (0.139)
AS-262	Buna O-Ring (70 DUROMETER)	7	7-1/4	1/8 (0.139)
AS-263	Buna O-Ring (70 DUROMETER)	7-1/4	7-1/2	1/8 (0.139)
AS-264	Buna O-Ring (70 DUROMETER)	7-1/2	7-3/4	1/8 (0.139)
AS-265	Buna O-Ring (70 DUROMETER)(s/a 5K74)	7-3/4	8	1/8 (0.139)
AS-266	Buna O-Ring (70 DUROMETER)	8	8-1/4	1/8 (0.139)
AS-267	Buna O-Ring (70 DUROMETER)	8-1/4	8-1/2	1/8 (0.139)
AS-268	Buna O-Ring (70 DUROMETER)	8-1/2	8-3/4	1/8 (0.139)
AS-269	Buna O-Ring (70 DUROMETER)	8-3/4	9	1/8 (0.139)
AS-270	Buna O-Ring (70 DUROMETER)	9	9-1/4	1/8 (0.139)
AS-271	Buna O-Ring (70 DUROMETER)	9-1/4	9-1/2	1/8 (0.139)
AS-272	Buna O-Ring (70 DUROMETER)	9-1/2	9-3/4	1/8 (0.139)
AS-273	Buna O-Ring (70 DUROMETER)	9-3/4	10	1/8 (0.139)
AS-274	Buna O-Ring (70 DUROMETER)	10	10-1/4	1/8 (0.139)
AS-275	Buna O-Ring (70 DUROMETER)	10-1/2	10-3/4	1/8 (0.139)
AS-276	Buna O-Ring (70 DUROMETER)	11	11-1/4	1/8 (0.139)
AS-277	Buna O-Ring (70 DUROMETER)	11-1/2	11-3/4	1/8 (0.139)
AS-278	Buna O-Ring (70 DUROMETER)	12	12-1/4	1/8 (0.139)
AS-279	Buna O-Ring (70 DUROMETER)	13	13-1/4	1/8 (0.139)
AS-280	Buna O-Ring (70 DUROMETER)	14	14-1/4	1/8 (0.139)
AS-281	Buna O-Ring (70 DUROMETER)	15	15-1/4	1/8 (0.139)
AS-282	Buna O-Ring (70 DUROMETER)	16	16-1/4	1/8 (0.139)
AS-283	Buna O-Ring (70 DUROMETER)	17	17-1/4	1/8 (0.139)
AS-284	Buna O-Ring (70 DUROMETER)	18	18-1/4	1/8 (0.139)
AS-309	Buna O-Ring (70 DUROMETER)	7/16	13-16	3/16 (0.210)
AS-310	Buna O-Ring (70 DUROMETER)	1/2	7/8	3/16 (0.210)
AS-311	Buna O-Ring (70 DUROMETER)	9/16	15/16	3/16 (0.210)
AS-312	Buna O-Ring (70 DUROMETER)	5/8	1	3/16 (0.210)
AS-313	Buna O-Ring (70 DUROMETER)	11/16	1-1/16	3/16 (0.210)
AS-314	Buna O-Ring (70 DUROMETER)	3/4	1-1/8	3/16 (0.210)
AS-315	Buna O-Ring (70 DUROMETER)	13/16	1-3/16	3/16 (0.210)



AS-316	Buna O-Ring (70 DUROMETER)	7/8	1-1/4	3/16 (0.210)
AS-317	Buna O-Ring (70 DUROMETER)	15/16	1-5/16	3/16 (0.210)
AS-318	Buna O-Ring (70 DUROMETER)	1	1-3/8	3/16 (0.210)
AS-319	Buna O-Ring (70 DUROMETER)	1-1/16	1-7/16	3/16 (0.210)
AS-320	Buna O-Ring (70 DUROMETER)	1-1/8	1-1/2	3/16 (0.210)
AS-321	Buna O-Ring (70 DUROMETER)	1-3/16	1-9/16	3/16 (0.210)
AS-322	Buna O-Ring (70 DUROMETER)	1-1/4	1-5/8	3/16 (0.210)
AS-323	Buna O-Ring (70 DUROMETER)	1-5/16	1-11/16	3/16 (0.210)
AS-324	Buna O-Ring (70 DUROMETER)	1-3/8	1-3/4	3/16 (0.210)
AS-325	Buna O-Ring (70 DUROMETER)	1-1/2	1-7/8	3/16 (0.210)
AS-326	Buna O-Ring (70 DUROMETER)	1-5/8	2	3/16 (0.210)
AS-327	Buna O-Ring (70 DUROMETER)	1-3/4	2-1/8	3/16 (0.210)
AS-328	Buna O-Ring (70 DUROMETER)	1-7/8	2-1/4	3/16 (0.210)
AS-329	Buna O-Ring (70 DUROMETER)	2	2-3/8	3/16 (0.210)
AS-330	Buna O-Ring (70 DUROMETER)	2-1/8	2-1/2	3/16 (0.210)
AS-331	Buna O-Ring (70 DUROMETER)	2-1/4	2-5/8	3/16 (0.210)
AS-332	Buna O-Ring (70 DUROMETER)	2-3/8	2-3/4	3/16 (0.210)
AS-333	Buna O-Ring (70 DUROMETER)	2-1/2	2-7/8	3/16 (0.210)
AS-334	Buna O-Ring (70 DUROMETER)	2-5/8	3	3/16 (0.210)
AS-335	Buna O-Ring (70 DUROMETER)	2-3/4	3-1/8	3/16 (0.210)
AS-336	Buna O-Ring (70 DUROMETER)	2-7/8	3-1/4	3/16 (0.210)
AS-337	Buna O-Ring (70 DUROMETER)	3	3-3/8	3/16 (0.210)
AS-338	Buna O-Ring (70 DUROMETER)	3-1/8	3-1/2	3/16 (0.210)
AS-339	Buna O-Ring (70 DUROMETER)	3-1/4	3-5/8	3/16 (0.210)
AS-340	Buna O-Ring (70 DUROMETER)	3-3/8	3-3/4	3/16 (0.210)
AS-341	Buna O-Ring (70 DUROMETER)	3-1/2	3-7/8	3/16

				(0.210)
AS-342	Buna O-Ring (70 DUROMETER)	3-5/8	4	3/16 (0.210)
AS-343	Buna O-Ring (70 DUROMETER)	3-3/4	4-1/8	3/16 (0.210)
AS-344	Buna O-Ring (70 DUROMETER)	3-7/8	4-1/4	3/16 (0.210)
AS-345	Buna O-Ring (70 DUROMETER)	4	4-3/8	3/16 (0.210)
AS-346	Buna O-Ring (70 DUROMETER)	4-1/8	4-1/2	3/16 (0.210)
AS-347	Buna O-Ring (70 DUROMETER)	4-1/4	4-5/8	3/16 (0.210)
AS-348	Buna O-Ring (70 DUROMETER)	4-3/8	4-3/4	3/16 (0.210)
AS-349	Buna O-Ring (70 DUROMETER)	4-1/2	4-7/8	3/16 (0.210)
AS-350	Buna O-Ring (70 DUROMETER)	4-5/8	5	3/16 (0.210)
AS-351	Buna O-Ring (70 DUROMETER)	4-3/4	5-1/8	3/16 (0.210)
AS-352	Buna O-Ring (70 DUROMETER)	4-7/8	5-1/4	3/16 (0.210)
AS-353	Buna O-Ring (70 DUROMETER)	5	5-3/8	3/16 (0.210)
AS-354	Buna O-Ring (70 DUROMETER)	5-1/8	5-1/2	3/16 (0.210)
AS-355	Buna O-Ring (70 DUROMETER)	5-1/4	5-5/8	3/16 (0.210)
AS-356	Buna O-Ring (70 DUROMETER)	5-3/8	5-3/4	3/16 (0.210)
AS-357	Buna O-Ring (70 DUROMETER)	5-1/2	5-7/8	3/16 (0.210)
AS-358	Buna O-Ring (70 DUROMETER)	5-5/8	6	3/16 (0.210)
AS-359	Buna O-Ring (70 DUROMETER)	5-3/4	6-1/8	3/16 (0.210)
AS-360	Buna O-Ring (70 DUROMETER)	5-7/8	6-1/4	3/16 (0.210)
AS-361	Buna O-Ring (70 DUROMETER)	6	6-3/8	3/16 (0.210)
AS-362	Buna O-Ring (70 DUROMETER)	6-1/4	6-5/8	3/16 (0.210)
AS-363	Buna O-Ring (70 DUROMETER)	6-1/2	6-7/8	3/16 (0.210)
AS-364	Buna O-Ring (70 DUROMETER)	6-3/4	7-1/8	3/16 (0.210)
AS-365	Buna O-Ring (70 DUROMETER)	7	7-3/8	3/16 (0.210)
AS-366	Buna O-Ring (70 DUROMETER)	7-1/4	7-5/8	3/16 (0.210)

AS-367	Buna O-Ring (70 DUROMETER)	7-1/2	7-7/8	3/16 (0.210)
AS-368	Buna O-Ring (70 DUROMETER)	7-3/4	8-1/8	3/16 (0.210)
AS-369	Buna O-Ring (70 DUROMETER)	8	8-3/8	3/16 (0.210)
AS-370	Buna O-Ring (70 DUROMETER)	8-1/4	8-5/8	3/16 (0.210)
AS-371	Buna O-Ring (70 DUROMETER)	8-1/2	8-7/8	3/16 (0.210)
AS-372	Buna O-Ring (70 DUROMETER)	8-3/4	9-1/8	3/16 (0.210)
AS-373	Buna O-Ring (70 DUROMETER)	9	9-3/8	3/16 (0.210)
AS-374	Buna O-Ring (70 DUROMETER)	9-1/4	9-5/8	3/16 (0.210)
AS-375	Buna O-Ring (70 DUROMETER)	9-1/2	9-7/8	3/16 (0.210)
AS-376	Buna O-Ring (70 DUROMETER)	9-3/4	10-1/8	3/16 (0.210)
AS-377	Buna O-Ring (70 DUROMETER)	10	10-3/8	3/16 (0.210)
AS-378	Buna O-Ring (70 DUROMETER)	10-1/2	10-7/8	3/16 (0.210)
AS-379	Buna O-Ring (70 DUROMETER)	11	11-3/8	3/16 (0.210)
AS-380	Buna O-Ring (70 DUROMETER)	11-1/2	11-7/8	3/16 (0.210)
AS-381	Buna O-Ring (70 DUROMETER)	12	12-3/8	3/16 (0.210)
AS-382	Buna O-Ring (70 DUROMETER)	13	13-3/8	3/16 (0.210)
AS-383	Buna O-Ring (70 DUROMETER)	14	14-3/8	3/16 (0.210)
AS-384	Buna O-Ring (70 DUROMETER)	15	15-3/8	3/16 (0.210)
AS-385	Buna O-Ring (70 DUROMETER)	16	16-3/8	3/16 (0.210)
AS-386	Buna O-Ring (70 DUROMETER)	17	17-3/8	3/16 (0.210)
AS-387	Buna O-Ring (70 DUROMETER)	18	18-3/8	3/16 (0.210)
AS-388	Buna O-Ring (70 DUROMETER)	19	19-3/8	3/16 (0.210)
AS-389	Buna O-Ring (70 DUROMETER)	20	20-3/8	3/16 (0.210)
AS-390	Buna O-Ring (70 DUROMETER)	21	21-3/8	3/16 (0.210)
AS-391	Buna O-Ring (70 DUROMETER)	22	22-3/8	3/16 (0.210)
AS-392	Buna O-Ring (70 DUROMETER)	23	23-3/8	3/16

				(0.210)
AS-393	Buna O-Ring (70 DUROMETER)	24	24-3/8	3/16 (0.210)
AS-394	Buna O-Ring (70 DUROMETER)	25	25-3/8	3/16 (0.210)
AS-395	Buna O-Ring (70 DUROMETER)	26	26-3/8	3/16 (0.210)
AS-406	Buna O-Ring (70 Durometer)	2-1/8	2-5/8	1/4 (0.275)
AS-413	Buna O-Ring (70 DUROMETER)(3" x .275)	3	3-1/2	1/4 (0.275)
AS-419	Buna O-Ring (70 DUROMETER)	3-3/4	4-1/4	1/4 (0.275)
AS-421	Buna O-Ring (70 DUROMETER)	4	4-1/2	1/4 (0.275)
AS-425	Buna O-Ring (70 DUROMETER)	4-1/2	5	1/4 (0.275)
AS-426	Buna O-Ring (70 DUROMETER)	4-5/8	5-1/8	1/4 (0.275)
AS-427	Buna O-Ring (70 DUROMETER)	4-3/4	5-1/4	1/4 (0.275)
AS-428	Buna O-Ring (70 DUROMETER)	4-7/8	5-3/8	1/4 (0.275)
AS-429	Buna O-Ring (70 DUROMETER)	5	5-1/2	1/4 (0.275)
AS-430	Buna O-Ring (70 DUROMETER)	5-1/8	5-5/8	1/4 (0.275)
AS-431	Buna O-Ring (70 DUROMETER)	5-1/4	5-3/4	1/4 (0.275)
AS-432	Buna O-Ring (70 DUROMETER) (Ref: 137x7)	5-3/8	5-7/8	1/4 (0.275)
AS-433	Buna O-Ring (70 DUROMETER)	5-1/2	6	1/4 (0.275)
AS-434	Buna O-Ring (70 DUROMETER)	5-5/8	6-1/8	1/4 (0.275)
AS-435	Buna O-Ring (70 DUROMETER)	5-3/4	6-1/4	1/4 (0.275)
AS-436	Buna O-Ring (70 DUROMETER)	5-7/8	6-3/8	1/4 (0.275)
AS-437	Buna O-Ring (70 DUROMETER)	6	6-1/2	1/4 (0.275)
AS-438	Buna O-Ring (70 DUROMETER)	6-1/4	6-3/4	1/4 (0.275)
AS-439	Buna O-Ring (70 DUROMETER)	6-1/2	7	1/4 (0.275)
AS-440	Buna O-Ring (70 DUROMETER)	6-3/4	7-1/4	1/4 (0.275)
AS-441	Buna O-Ring (70 DUROMETER)	7	7-1/2	1/4 (0.275)
AS-442	Buna O-Ring (70 DUROMETER)	7-1/4	7-3/4	1/4 (0.275)
AS-443	Buna O-Ring (70 DUROMETER)	7-1/2	8	1/4 (0.275)
AS-444	Buna O-Ring (70 DUROMETER)	7-3/4	8-1/4	1/4 (0.275)
AS-445	Buna O-Ring (70 DUROMETER)	8	8-1/2	1/4 (0.275)
AS-446	Buna O-Ring (70 DUROMETER)	8-1/2	9	1/4 (0.275)
AS-447	Buna O-Ring (70 DUROMETER)	9	9-1/2	1/4 (0.275)

AS-448	Buna O-Ring (70 DUROMETER) (Ref: 240 x 7)	9-1/2	10	1/4 (0.275)
AS-449	Buna O-Ring (70 DUROMETER)	10	10-1/2	1/4 (0.275)
AS-450	Buna O-Ring (70 DUROMETER)	10-1/2	11	1/4 (0.275)
AS-451	Buna O-Ring (70 DUROMETER)	11	11-1/2	1/4 (0.275)
AS-452	Buna O-Ring (70 DUROMETER)	11-1/2	12	1/4 (0.275)
AS-453	Buna O-Ring (70 DUROMETER)	12	12-1/2	1/4 (0.275)
AS-454	Buna O-Ring (70 DUROMETER)	12-1/2	13	1/4 (0.275)
AS-455	Buna O-Ring (70 DUROMETER)	13	13-1/2	1/4 (0.275)
AS-456	Buna O-Ring (70 DUROMETER)	13-1/2	14	1/4 (0.275)
AS-457	Buna O-Ring (70 DUROMETER)	14	14-1/2	1/4 (0.275)
AS-458	Buna O-Ring (70 DUROMETER)	14-1/2	15	1/4 (0.275)
AS-459	Buna O-Ring (70 DUROMETER)	15	15-1/2	1/4 (0.275)
AS-460	Buna O-Ring (70 DUROMETER)	15-1/2	16	1/4 (0.275)
AS-461	Buna O-Ring (70 DUROMETER)	16	16-1/2	1/4 (0.275)
AS-462	Buna O-Ring (70 DUROMETER)	16-1/2	17	1/4 (0.275)
AS-463	Buna O-Ring (70 DUROMETER)	17	17-1/2	1/4 (0.275)
AS-464	Buna O-Ring (70 DUROMETER)	17-1/2	18	1/4 (0.275)
AS-465	Buna O-Ring (70 DUROMETER)	18	18-1/2	1/4 (0.275)
AS-466	Buna O-Ring (70 DUROMETER)	18-1/2	19	1/4 (0.275)
AS-467	Buna O-Ring (70 DUROMETER)	19	19-1/2	1/4 (0.275)
AS-468	Buna O-Ring (70 DUROMETER)	19-1/2	20	1/4 (0.275)
AS-469	Buna O-Ring (70 DUROMETER)	20	20-1/2	1/4 (0.275)
AS-470	Buna O-Ring (70 DUROMETER)	21	21-1/2	1/4 (0.275)
AS-471	Buna O-Ring (70 DUROMETER)	22	22-1/2	1/4 (0.275)
AS-472	Buna O-Ring (70 DUROMETER)	23	23-1/2	1/4 (0.275)
AS-473	Buna O-Ring (70 DUROMETER)	24	24-1/2	1/4 (0.275)
AS-474	Buna O-Ring (70 DUROMETER)	25	25-1/2	1/4 (0.275)
AS-475	Buna O-Ring (70 DUROMETER)	26	26-1/2	1/4 (0.275)
AS-901	Buna O-Ring (70 DUROMETER)	.185	3/32 Tube	.056
AS-902	Buna O-Ring (70 DUROMETER)	.239	1/8 Tube	.064
AS-903	Buna O-Ring (70 DUROMETER)	.301	3/16 Tube	.064
AS-904	Buna O-Ring (70 DUROMETER)	.351	1/4 Tube	.072
AS-905	Buna O-Ring (70 DUROMETER)	.414	5/16 Tube	.072

AS-906	Buna O-Ring (70 DUROMETER)	.468	3/8 Tube	.078
AS-907	Buna O-Ring (70 DUROMETER)	.530	7/16 Tube	.082
AS-908	Buna O-Ring (70 DUROMETER)	.644	1/2 Tube	.087
AS-909	Buna O-Ring (70 DUROMETER)	.706	9/16 Tube	.097
AS-910	Buna O-Ring (70 DUROMETER)	.755	5/8 Tube	.097
AS-911	Buna O-Ring (70 DUROMETER)	.863	11/16 Tube	.116
AS-912	Buna O-Ring (70 DUROMETER)	.924	3/4 Tube	.116
AS-913	Buna O-Ring (70 DUROMETER)	.986	13/16 Tube	.116
AS-914	Buna O-Ring (70 DUROMETER)	1.047	7/8 Tube	.116
AS-916	Buna O-Ring (70 DUROMETER)	1.171	1 Tube	.116
AS-918	Buna O-Ring (70 DUROMETER)	1.355	1-1/8 Tube	.116
AS-920	Buna O-Ring (70 DUROMETER)	1.475	1-1/4 Tube	.118
AS-924	Buna O-Ring (70 DUROMETER)	1.720	1-1/2 Tube	.118
AS-928	Buna O-Ring (70 DUROMETER)	2.090	1-3/4 Tube	.118
AS-932	Buna O-Ring (70 DUROMETER)	2.337	2 Tube	.118

---